



1630 W 11th ST, UNIT E, UPLAND, CA 91786

909.946.2942, 909.985.2301 FAX

www.hinsonracing.com

H557-IH-2101

KX250 INNER HUB

Congratulations, you have just purchased the finest inner hub available. Manufactured from T-6 aircraft aluminum with tolerances to aircraft specs and anodized for improved durability. Used by Team Honda, Team Red Bull KTM, and Team Pro Circuit Kawasaki.

Crucial Inspection

If your clutch has a jutter spring and seat ring, located at the bottom of your clutch pack against the inner hub, **these need to be removed**

Instructions:

1. Drain engine oil and remove cover and gasket
2. Remove 5 stock pressure plate bolts and holders, stopper plate, spring, & pressure plate
3. Remove main shaft nut, washer, and oem inner hub
4. Install new Hinson inner hub and oem washer and main shaft nut and torque to your manufactures recommended torque spec. (note the oem nut is crimped from the factory and we recommend replacing this nut with a new oem one to ensure it will not come loose)
5. Re Install pressure plate, spring, stopper plate, and spring holders and bolts and tighten to manufactures specification being sure to keep the spring as centered as possible
6. Reinstall clutch cover being sure to inspect gasket before reinstalling
7. Refill with engine oil

For the best performance and life from your clutch assembly, we recommend you install new Hinson clutch plates. Also, we recommend using a petroleum based 10w-40 Racing Engine Oil and that you change your oil after each time you ride. We recommend you soak your clutch plates in oil before you install them. Do not use Kevlar or Carbon Fiber clutch plates as they will cause excessive wear and may void your warranty.

To see more parts available for this model visit us at HinsonRacing.com

Thank you for purchasing a Hinson Clutch Components product. If you have any questions or need technical assistance, please call us at (909) 946-2942 or email us:


Info@hinsonracing.com



If your clutch has a jutter spring and seat located at the bottom of your clutch pack against the inner hub, **these both need to be removed.**

Jutter Spring on Inner Hub

Jutter Spring & Seat



Warranty information

All merchandise manufactured by Hinson Clutch Components is guaranteed against defects in material and workmanship for a period of six months from the original date of purchase. Use of Kevlar and carbon fiber clutch plates will cause excessive wear and will void your warranty. Hinson Clutch Components will not warranty any product that has been modified, or where the product became defective due to improper installation, improper use, or any other misuse of the product. Hinson Clutch Components shall not be liable for any other damages caused by any defects in the product, whether incidental, consequential or otherwise. If your product is defective we will, at our discretion, repair or replace the product after it is returned to Hinson Clutch Components for a warranty inspection. Any request for warranty assistance will require your original receipt or acceptable proof of purchase. Hinson Clutch Components liability is limited to the cost of repair or replacement of the product. All warranty items will be viewed and acted upon at the discretion of Hinson Clutch Components.

Thank you very much for purchasing a Hinson Clutch Component!